# DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

1594 West North Temple, Suite 1210

Kathleen Clarke 801-538-5340 Executive Director 801-359-3940 (Fax)

Governor

Lowell P. Braxton Division Director

Michael O. Leavitt

PO Box 145801 Salt Lake City, Utah 84114-5801

801-538-7223 (TDD)

Exploration:

INSPECTION REPORT

Partial: XXX Complete:\_\_\_\_ Inspection Date & Time: 10/24/2001 / 8:00 - 14:00 Date of Last Inspection: <u>09/12/2001</u>

Mine Name: Star Point Mine	County: Carbon	Permit Number: <u>C/007/006</u>	•			
Permittee and/or Operator's Name:	Plateau Mining Corporation	L				
Business Address: 847 Northwest Highway 191, Helper, Utah 84526						
Type of Mining Activity: Undergrou	nd XXX Surface	Prep. Plant Other	er			
Company Official(s): Johnny Pappa	as					
State Official(s): Karl R. Houskeepe	erFederal Official(s): No	one				
Weather Conditions: Clear & Cool,						
Existing Acreage: Permitted 9084	Disturbed <u>213.4</u> Re	graded Seeded				
Status: Active Reclamation XXX		_				

# REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

- Substantiate the elements on this inspection by checking the appropriate performance standard.
  - For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
  - For partial inspections check only the elements evaluated.
- Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

		EVALUATED	N/A	<b>COMMENTS</b>	NOV/ENF
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	Ш	П	П	Ц
2.	SIGNS AND MARKERS	[X]	$\Box$	[X]	$\Box$
3.	TOPSOIL	[X]	$\Box$	[X]	$\Box$
4.	HYDROLOGIC BALANCE:				
	a. DIVERSIONS	[X]		[X]	$\Box$
	b. SEDIMENT PONDS AND IMPOUNDMENTS	[X]	$\Box$	[X]	$\Box$
	c. OTHER SEDIMENT CONTROL MEASURES	[X]		[X]	$\Box$
	d. WATER MONITORING	[X]	$\Box$	[X]	П
	e. EFFLUENT LIMITATIONS	-[_]	$\Box$	П	$\Box$
5.	EXPLOSIVES	П	$\Box$	Ц	П
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	П	$\Box$	$\Box$	$\Box$
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	[X]	$\Box$	П	$\Box$
8.	NONCOAL WASTE	[X]	$\Box$	Ц	П
9.	PROTECTION OF FISH, WILDLIFE AND RELATED				
	ENVIRONMENTAL ISSUES		П	Ц	Ц
10.	SLIDES AND OTHER DAMAGE	$\Box$	$\Box$	Ц	П
11.	CONTEMPORANEOUS RECLAMATION	∐ -	П	$\Box$	Ц
12.	BACKFILLING AND GRADING	$\Box$	П	$\Box$	$\Box$
13.	REVEGETATION	$\Box$	П	$\Box$	$\Box$
14.	SUBSIDENCE CONTROL	$\Box$	Ц	П	$\Box$
15.	CESSATION OF OPERATIONS	$\Box$	П	$\Box$	$\Box$
16.	ROADS:				
	a. CONSTRUCTION/MAINTENANCE/SURFACING	[X]	$\Box$	[X]	$\prod_{i}$
	b. DRAINAGE CONTROLS	[X]	Ц	[X]	$\Box$
17.	OTHER TRANSPORTATION FACILITIES	$\Box$	П	$\Box$	$\Box$
18.	SUPPORT FACILITIES/UTILITY INSTALLATIONS	П	$\Box$		$\Box$
19.	AVS CHECK (4th Quarter- April, May, June)	П	П		П
20.	AIR QUALITY PERMIT	П	$\Box$		$\Box$
21.	BONDING & INSURANCE		$\Box$	$\Box$	$\Box$

#### INSPECTION REPORT

(Continuation sheet)

PERMIT NUMBER: C/007/006

DATE OF INSPECTION: 10/24/2001

( COMMENTS ARE NUMBERED TO CORRESPOND WITH TOPICS LISTED ABOVE )

#### 2. SIGNS AND MARKERS

All markers are in place as required by the coal rules. The ID sign is in place. It is located near the permit boundary within the disturbed area.

#### 3. TOPSOIL

The soil piles are protected from erosion with alternative sediment control devices.

#### 4A. HYDROLOGIC BALANCE: DIVERSIONS

There are approximately sixteen miles of constructed diversions within the disturbed and interfacing undisturbed area. This includes water conveyance systems of over 80 ditches and 32 culverts and berms that control and direct runoff. Repairs to the diversions have been completed since the last inspection.

#### 4B. HYDROLOGIC BALANCE: SEDIMENT PONDS AND IMPOUNDMENTS

There are nine sediment ponds and three water impoundments. The sediment ponds provide sediment control for the majority of the disturbed areas. There are four BTCA's. The runoff from these areas is treated and controlled by alternative sediment control measures. The water impoundments are associated with the coal wash plant. No hazardous conditions were noticed. No discharges were taking place.

#### 4C. HYDROLOGIC BALANCE: OTHER SEDIMENT CONTROL MEASURES

Silt fences provide the sediment control on the BTCA areas. The mine has installed redundant sediment control measures including straw bales, silt fences, sumps, and check dams to retain sediment near the source. All of the sediment control structures have been maintained and are functional.

### 4D. HYDROLOGIC BALANCE: WATER MONITORING

The third quarter water monitoring has been done and will be submitted to the Division. The second quarter water monitoring has been submitted and is in the EDI pipeline.

## 16A. ROADS: CONSTRUCTION/MAINTENANCE/SURFACING

The roads are designed and are included in the MRP. The roads have been re-graded and are being maintained.

The operator has installed chain link fencing around the mine office and warehouse area. The Lion Deck road is open for public access to the top of Gentry Mountain. The previous public access was the road through the #1 Mine area that is currently being reclaimed.

### INSPECTION REPORT

(Continuation sheet)

PERMIT NUMBER: <u>C/007/006</u>

DATE OF INSPECTION: 10/24/2001

#### 16B. **ROADS: DRAINAGE CONTROLS**

The ditches along the road have been re-established using a road grader and back hoe. The Silt Fences used to treat the road runoff have been cleaned and are in good shape. Extensive efforts have been taken by the operator to maintain the inactive site in preparation for reclamation.

Inspector's Signature:

Karl R. Houskeeper

Date: October 25, 2001

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas & Mining.

James Fulton, OSM

Johnny Pappas, Plateau Mining

Price Field office

O:\007006.STP\Compliance\2001\p\_1024.wpd